



Paint Stripper That Works!®



- ⇒ **No Methylene Chloride**
- ⇒ **No Caustics**
- ⇒ **No Acids**

This 18' wooden boat was sprayed with Star 10 'Phase 1 Paste', allowed to dwell for two hours and power washed clean.

1952 Shellake "Lady Gull" Cruiser



Project below almost complete. Notice how clean the interior wood became. The cruiser floor was coated with bottom paint and the rest of the boat was coated with a marine varnish.

- ⇒ Leaves the surface **neutral**
- ⇒ **Immediate** refinishing
- ⇒ **Will not** burn your skin
- ⇒ **Will not** darken the wood

Visit our web site for more
projects
www.starten.com

E-mail: sales@starten.com

800-726-4319

